

RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

							3233113 TIME . 10.00.00			
SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE	
1		ITEM-00001	URGENT REPAIR OF ENGINE STARTER AT BBAYCREK 132KV SUBSTATION.ISSUE: STARTER MOTOR FOUND FAULTY.MAKE: DEUTZ; MODEL: DFP6-2012-C10; SERIAL # 11229448INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INST ALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW A ND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN.ANEEZ.	1	AU					
			ABDULRAZAK@DEWA.GOV.AE, 04-3221323,							
2		ITEM-00002	URGENT REPAIR OF ENGINE STARTER AT BRES 132KV SUBSTATION.ISSUE: STARTER MOTOR	1	AU					



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			FOUND FAULTY. TACH HOUR METER NOT WORKINGMAKE: CLARKE; MODEL: JU6H-UFG8; SERIAL # PE-6068T673115INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ						
3		ITEM-00003	04-3221323, REPLACEMENT OF TACH HOUR METER IN FIRE DIESEL ENGINE AT DLVL 132KVSUBSTATION.ISSUE:	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TACH HOUR METER / RPM METER FOUND						
			DEFECTIVE.MAKE						
			: CLARKE; MODEL: JU6H-UFG8 ; SERIAL #						
			PE-6068T661687INTERESTED PARTIES MUST DO						
			SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUD						
			ES SUPPLY OF NECESSARY SPARES,						
			INSTALLATION AND SUCCESSFULTEST RUN OF						
			DIESEL PUMP SET. WORK TO BE COMPLETED						
			WITHIN 14 DAYS OF PORECE						
			IPT. THE VENDOR MUST BE EXPERIENCED IN						
			SERVICING UL\FM APPROVED FIREDIESEL						
			ENGINES AND HAVE OWN FACILITY FOR REPAIR						
			AND SERVICING. O						
			NLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND						
			SITE VISIT, PLEASE CONTACT ENGR.						
			SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						
			29325FOR OTHER ENQUI						
			RIES, CONTACT ENGR. ANEEZ						
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
4		ITEM-00004	REPLACEMENT OF TACH HOUR METER IN FIRE	1	AU				
			DIESEL ENGINE AT TCRA						



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KVSUBSTATION.ISSUE: TACH HOUR METER /						
			RPM METER FOUND DEFECTIVE.MAKE						
			: CLARKE; MODEL: JU6H-UFG8 ; SERIAL #						
			PF6068T759748SAP WORK ORDER #						
			521156774INTERESTED PARTIES MUST DO SITE						
			VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPPLY OF						
			NECESSARY SPARES, INSTALLATION AND						
			SUCCESSFULTEST RUN OF DIESEL PUMP SET.						
			WORK TO BE COMPLETED						
			WITHIN 14 DAYS OF PORECEIPT. THE VENDOR						
			MUST BE EXPERIENCED IN SERVICING UL\FM						
			APPROVED FIREDIESEL ENGINES AND HAVE OWN						
			FACILITY FO						
			R REPAIR AND SERVICING. ONLY OEMPARTS WILL						
			BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE						
			CONTACT ENGR.						
			SRIHARI,SRIHARI.R@DEWA.GOV.AE, 0						
			4-32 29325FOR OTHER ENQUIRIES, CONTACT						
			ENGR. ANEEZ						
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
5		ITEM-00005	REPLACEMENT OF FUEL GAUGE IN FIRE DIESEL	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE AT OXYGEN 132KVSUBSTATION.ISSUE: DIESEL ENGINE FUEL GAUGE FOUND FAULTYMAKE: CLARKE; MODEL: JU6H-UF30; SERIAL # PE6068E001175INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY O F NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VE NDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WI LL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT E NGR. ANEEZ						PRICE
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE						
			SHOWING HIGH TEMPERATUREMAKE: CLARKE;						
			MODEL: JU6H-						
			UFM2; SERIAL # PE6068T767207INTERESTED						
			PARTIES MUST DO SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPPLY OF						
			NECESSARY S						
			PARES, INSTALLATION AND SUCCESSFULTEST						
			RUN OF DIESEL PUMP SET. WORK TO BE						
			COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE						
			VENDOR MUST BE						
			EXPERIENCED IN SERVICING UL\FM APPROVED						
			FIREDIESEL ENGINES AND HAVE FACILITY FOR						
			REPAIR AND SERVICING. ONLY OEMPARTS WILL BE						
			ACCEPTE						
			D.FOR PTW AND SITE VISIT, PLEASE CONTACT						
			ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						
			29325FOR OTHER ENQUIRIES, CONTACT ENGR.						
			ANEEZ HU						
			SAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
7		ITEM-00007	URGENT REPAIR OF FIRE DIESEL ENGINE AT	1	AU				
			KHILROAD 132KV SUBSTATION.ISSUE: DIESEL						



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE EXHAUST PIPE OUTSIDE FLAPPER						
			DAMAGED.MAKE: CLA						
			RKE; MODEL: JU6H-UF52; SERIAL #						
			PE6068E000980INTERESTED PARTIES MUST DO						
			SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPP						
			LY OF NECESSARY SPARES, INSTALLATION AND						
			SUCCESSFULTEST RUN OF DIESEL PUMP SET.						
			WORK TO BE COMPLETED WITHIN 14 DAYS OF						
			PORECEIPT. TH						
			E VENDOR MUST BE EXPERIENCED IN SERVICING						
			UL\FM APPROVED FIREDIESEL ENGINES AND HAVE						
			THEIR OWN FACILITY FOR REPAIR AND						
			SERVICING.ONL						
			Y OEM PARTS WILL BE ACCEPTED. HIGH LEVEL						
			ACCESS ARRANGEMENT ISCONTRACTOR						
			SCOPEFOR PTW AND SITE VISIT, PLEASE CONTACT						
			ENGR. SRIHARI,S						
			RIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER						
			ENQUIRIES, CONTACT ENGR. ANEEZ						
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
8		ITEM-00008	URGENT REPAIR OF FIRE DIESEL ENGINE AT WTSC	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08,2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE						
			COOLING LINE DAMAGEDMAKE: CLARKE; MODEL:						
			JU6H-UFM2						
			; SERIAL # PF6068T745112INTERESTED PARTIES						
			MUST DO SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPPLY OF						
			NECESSARY SPARE						
			S, INSTALLATION AND SUCCESSFULTEST RUN OF						
			DIESEL PUMP SET. WORK TO BE COMPLETED						
			WITHIN 14 DAYS OF PORECEIPT. THE VENDOR						
			MUST BE EXPE						
			RIENCED IN SERVICING UL\FM APPROVED						
			FIREDIESEL ENGINES AND HAVE THEIR OWN						
			FACILITY FOR REPAIR AND SERVICING.ONLY OEM						
			PARTS WILL BE A						
			CCEPTED.FOR PTW AND SITE VISIT, PLEASE						
			CONTACT ENGR.						
			SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						
			29325FOR OTHER ENQUIRIES, CONTACT ENGR. AN						
			EEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

SPECIAL NOTES / INSTRUCTIONS:

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

							3233113 TIME . 10.00.00			
SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE	
1		ITEM-00001	URGENT REPAIR OF ENGINE STARTER AT BBAYCREK 132KV SUBSTATION.ISSUE: STARTER MOTOR FOUND FAULTY.MAKE: DEUTZ; MODEL: DFP6-2012-C10; SERIAL # 11229448INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INST ALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW A ND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN.ANEEZ.	1	AU					
			ABDULRAZAK@DEWA.GOV.AE, 04-3221323,							
2		ITEM-00002	URGENT REPAIR OF ENGINE STARTER AT BRES 132KV SUBSTATION.ISSUE: STARTER MOTOR	1	AU					



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			FOUND FAULTY. TACH HOUR METER NOT WORKINGMAKE: CLARKE; MODEL: JU6H-UFG8; SERIAL # PE-6068T673115INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ						
3		ITEM-00003	04-3221323, REPLACEMENT OF TACH HOUR METER IN FIRE DIESEL ENGINE AT DLVL 132KVSUBSTATION.ISSUE:	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TACH HOUR METER / RPM METER FOUND						
			DEFECTIVE.MAKE						
			: CLARKE; MODEL: JU6H-UFG8 ; SERIAL #						
			PE-6068T661687INTERESTED PARTIES MUST DO						
			SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUD						
			ES SUPPLY OF NECESSARY SPARES,						
			INSTALLATION AND SUCCESSFULTEST RUN OF						
			DIESEL PUMP SET. WORK TO BE COMPLETED						
			WITHIN 14 DAYS OF PORECE						
			IPT. THE VENDOR MUST BE EXPERIENCED IN						
			SERVICING UL\FM APPROVED FIREDIESEL						
			ENGINES AND HAVE OWN FACILITY FOR REPAIR						
			AND SERVICING. O						
			NLY OEMPARTS WILL BE ACCEPTED.FOR PTW AND						
			SITE VISIT, PLEASE CONTACT ENGR.						
			SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						
			29325FOR OTHER ENQUI						
			RIES, CONTACT ENGR. ANEEZ						
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
4		ITEM-00004	REPLACEMENT OF TACH HOUR METER IN FIRE	1	AU				
			DIESEL ENGINE AT TCRA						



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KVSUBSTATION.ISSUE: TACH HOUR METER /						
			RPM METER FOUND DEFECTIVE.MAKE						
			: CLARKE; MODEL: JU6H-UFG8 ; SERIAL #						
			PF6068T759748SAP WORK ORDER #						
			521156774INTERESTED PARTIES MUST DO SITE						
			VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPPLY OF						
			NECESSARY SPARES, INSTALLATION AND						
			SUCCESSFULTEST RUN OF DIESEL PUMP SET.						
			WORK TO BE COMPLETED						
			WITHIN 14 DAYS OF PORECEIPT. THE VENDOR						
			MUST BE EXPERIENCED IN SERVICING UL\FM						
			APPROVED FIREDIESEL ENGINES AND HAVE OWN						
			FACILITY FO						
			R REPAIR AND SERVICING. ONLY OEMPARTS WILL						
			BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE						
			CONTACT ENGR.						
			SRIHARI,SRIHARI.R@DEWA.GOV.AE, 0						
			4-32 29325FOR OTHER ENQUIRIES, CONTACT						
			ENGR. ANEEZ						
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
5		ITEM-00005	REPLACEMENT OF FUEL GAUGE IN FIRE DIESEL	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE AT OXYGEN 132KVSUBSTATION.ISSUE: DIESEL ENGINE FUEL GAUGE FOUND FAULTYMAKE: CLARKE; MODEL: JU6H-UF30; SERIAL # PE6068E001175INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY O F NECESSARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VE NDOR MUST BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE FACILITY FOR REPAIR AND SERVICING. ONLY OEMPARTS WI LL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER ENQUIRIES, CONTACT E NGR. ANEEZ						PRICE
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE						
			SHOWING HIGH TEMPERATUREMAKE: CLARKE;						
			MODEL: JU6H-						
			UFM2; SERIAL # PE6068T767207INTERESTED						
			PARTIES MUST DO SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPPLY OF						
			NECESSARY S						
			PARES, INSTALLATION AND SUCCESSFULTEST						
			RUN OF DIESEL PUMP SET. WORK TO BE						
			COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE						
			VENDOR MUST BE						
			EXPERIENCED IN SERVICING UL\FM APPROVED						
			FIREDIESEL ENGINES AND HAVE FACILITY FOR						
			REPAIR AND SERVICING. ONLY OEMPARTS WILL BE						
			ACCEPTE						
			D.FOR PTW AND SITE VISIT, PLEASE CONTACT						
			ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						
			29325FOR OTHER ENQUIRIES, CONTACT ENGR.						
			ANEEZ HU						
			SAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
7		ITEM-00007	URGENT REPAIR OF FIRE DIESEL ENGINE AT	1	AU				
			KHILROAD 132KV SUBSTATION.ISSUE: DIESEL						



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

							-		
SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ENGINE EXHAUST PIPE OUTSIDE FLAPPER						
			DAMAGED.MAKE: CLA						
			RKE; MODEL: JU6H-UF52; SERIAL #						
			PE6068E000980INTERESTED PARTIES MUST DO						
			SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPP						
			LY OF NECESSARY SPARES, INSTALLATION AND						
			SUCCESSFULTEST RUN OF DIESEL PUMP SET.						
			WORK TO BE COMPLETED WITHIN 14 DAYS OF						
			PORECEIPT. TH						
			E VENDOR MUST BE EXPERIENCED IN SERVICING						
			UL\FM APPROVED FIREDIESEL ENGINES AND HAVE						
			THEIR OWN FACILITY FOR REPAIR AND						
			SERVICING.ONL						
			Y OEM PARTS WILL BE ACCEPTED. HIGH LEVEL						
			ACCESS ARRANGEMENT ISCONTRACTOR						
			SCOPEFOR PTW AND SITE VISIT, PLEASE CONTACT						
			ENGR. SRIHARI,S						
			RIHARI.R@DEWA.GOV.AE, 04-32 29325FOR OTHER						
			ENQUIRIES, CONTACT ENGR. ANEEZ						
			HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						
8		ITEM-00008	URGENT REPAIR OF FIRE DIESEL ENGINE AT WTSC	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE GAUGE PANEL RECTIFIER FOUND.MAKE: CLARKE; MODEL: J U6H-UFG8; SERIAL # PE6068T794934INTERESTED PARTIES MUST DO SITE VISIT AND EVALUATE THE REQUIREMENTS.SCOPE INCLUDES SUPPLY OF NECESS ARY SPARES, INSTALLATION AND SUCCESSFULTEST RUN OF DIESEL PUMP SET. WORK TO BE COMPLETED WITHIN 14 DAYS OF PORECEIPT. THE VENDOR MUS T BE EXPERIENCED IN SERVICING UL\FM APPROVED FIREDIESEL ENGINES AND HAVE THEIR OWN FACILITY FOR REPAIR AND SERVICING.ONLY OEM PARTS WILL BE ACCEPTED.FOR PTW AND SITE VISIT, PLEASE CONTACT ENGR. SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						PRICE
			29325FOR OTHER ENQUIRIES, CONTACT ENGR. ANEEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE, 04-3221323,						
9		ITEM-00009	URGENT REPAIR OF FIRE DIESEL ENGINE AT DSOS	1	AU				



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

CLOSING DATE : 07.08,2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			132KV SUBSTATION.ISSUE: DIESEL ENGINE						
			COOLING LINE DAMAGEDMAKE: CLARKE; MODEL:						
			JU6H-UFM2						
			; SERIAL # PF6068T745112INTERESTED PARTIES						
			MUST DO SITE VISIT AND EVALUATE THE						
			REQUIREMENTS.SCOPE INCLUDES SUPPLY OF						
			NECESSARY SPARE						
			S, INSTALLATION AND SUCCESSFULTEST RUN OF						
			DIESEL PUMP SET. WORK TO BE COMPLETED						
			WITHIN 14 DAYS OF PORECEIPT. THE VENDOR						
			MUST BE EXPE						
			RIENCED IN SERVICING UL\FM APPROVED						
			FIREDIESEL ENGINES AND HAVE THEIR OWN						
			FACILITY FOR REPAIR AND SERVICING.ONLY OEM						
			PARTS WILL BE A						
			CCEPTED.FOR PTW AND SITE VISIT, PLEASE						
			CONTACT ENGR.						
			SRIHARI,SRIHARI.R@DEWA.GOV.AE, 04-32						
			29325FOR OTHER ENQUIRIES, CONTACT ENGR. AN						
			EEZ HUSAIN,ANEEZ.ABDULRAZAK@DEWA.GOV.AE,						
			04-3221323,						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:



RFQ NUMBER : 2332501944

DATE : 31.07.2025

REQ No : 1032503597

REQ TITLE : Urgent repair 1032503676

DELIVERY LOCATION

SPECIAL NOTES / INSTRUCTIONS:

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP