

RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	TREATPLT: REFUBRISHMENT OF DANFOSS 1.5 "DSVTHE SCOPE OF WORK FOR REFURBISHMENT OF EUROSAFE MAKE WATER MIST SYSTEMMOTORIZED DRY SECTI ONAL VALVES [SIZES 1INCH & 1.5 INCH] SHALL INCLUDE,NOT LIMITED TO THE FOLLOWING, INSPECTION, PREPARATIONS AND REPLACEMENTOF PARTS AS APPLICABLE AS FOLLOWS:-INSPECTION AND PREPARATION##THE CONTRACTOR MUST HAVE EXPERIENCE IN REPAIR AND RECTIFICATION OFEUROSAFE MAKE HP WATER MIST SYSTEM.##CLEAN INTERNAL COMPONENTS USING SUITABLE SOLVENTS.##REMOVE SCALE, RUST, OR DEBRIS USING BRUSHES##DRY ALL PART S THOROUGHLY WITH LINT-FREE CLOTHS OR COMPRESSED AIR.##CHECK BALL SURFACE FOR SCORING, PITTING, OR CORROSION.##EXAMINE SEATS AND SEA LS FOR WEAR, DEFORMATION, OR	1	EA				PRICE
			RINGS OF THE BALL VALVE.##CHECK ACTUATOR						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			FOR SMOOTH OPERATIO						
			N, AND SIGNAL RESPONSE.##THE REPLACEMENT						
			OF COMPONENTS IF INVOLVED SHALL BE OF SAME						
			MAKE &MODEL OF THAT OF OEM.##ALL THE						
			TESTING SHA						
			LL BE CARRIED OUT IN THE VENDOR TEST						
			FACILITY ORANY APPROVED TESTING						
			LABORATORY.##A PROPER INSPECTION REPORT						
			WITH PHOTOGRAPHS SHALL						
			BE SUBMITTED TODEWACASE: -1 ACTUATOR IS						
			WORKING PERFECTLY, AND VALVE NEED TO BE						
			RECTIFIEDRECTIFICATION OF DSV##REPLACE						
			DAMAGED TEFLO						
			N PAD ON THE BALL VALVE.##LAP THE BALL AND						
			SEATS IF MINOR DAMAGE EXISTS.##LUBRICATE						
			MOVING PARTS WITH APPROPRIATE VALVE						
			GREASE.##REA						
			SSEMBLE VALVE IN CORRECT ORIENTATION AND						
			TORQUE FASTENERS TOSPECIFICATION.##DO THE						
			HYDRAULIC STATIC PRESSURE TEST WITH						
			PRESSURE OF 2						
			10 BARS FOR15 MIN.##IF THE PRESSURE TEST IS						
			PASSED MOUNT ACTUATOR, ALIGN TO						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PREVIOUSPOSITION, AND TIGHTEN						
			PROPERLY.##CONNECT ELECTRI						
			CAL LINES AS PER SPECIFICATIONS.##CALIBRATE						
			ACTUATOR STROKE USING MANUAL						
			TUNING.##ENSURE SMOOTH OPERATION OF VALVE						
			AND ACTUATOR ASSE						
			MBLY.##IF THE PRESSURE TEST FAILS DISPOSE						
			THE VALVE##PROPOSE AND ASSEMBLE NEW						
			VALVE TO THE ACTUATOR AND TEST						
			AGAIN.##GENERATE VALVE						
			REFURBISHMENT/REPLACEMENT REPORT WITH						
			BEFORE AND AFTERPHOTOGRAPHS##WARRANTY						
			FOR THE NEW VALVE SUPPLIED: 1 YEAR CASE: -2						
			VALVE IS FUN						
			CTIONING PERFECTLY, AND ACTUATOR IS NOT						
			WORKING##CHECK ACTUATOR FOR SMOOTH						
			OPERATION, AND SIGNAL RESPONSE.##CLEAN THE						
			MOVING PARTS A						
			ND LUBRICATE##CONNECT ELECTRICAL LINES AS						
			PER SPECIFICATIONS AND TEST##IF THE VALVE IS						
			NOT WORKING, REPLACE THE ACTUATOR [ULLI 10						
			SE						
			RIESJAND ASSEMBLE TO THE VALVE AND DO THE						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TESTING.##CONNECT ELECTRICAL LINES AS PER SPECIFICATIONS.##CALIBRATE ACTUATOR STROKE USING MANUAL TUNING.##ENSURE SMOOTH OPERATION OF VALVE AND ACTUATOR ASSEMBLY.##DO THE HYDRAULIC STATIC PRESSURE TEST WITH PRESSURE OF 210 BARS FOR15 MIN.##GENERATE VALVE REFURBISHMENT/REPLACEMENT REPORT WITH BEFORE AND AFTERPHOTOGRAPHS##WARRANTY FOR THE NEW ACTUATOR SU PPLIED: 1 YEARTHE WORK SHALL BE COMPLETED WITHIN 4 WEEKS FROM DATE OF ISSUANCE OF PO.FOR ANY RELATED QUERIES AND FURTHER INFORMATION , CONTACT MR. VISHNUVIJAY [EMAIL: VISHNU.VIJAY@DEWA.GOV.AE, MOB: 0509463644] OR MR. ANEEZHUSSAIN [EMAIL: ANEEZ.ABDULRAZAK@DEWA.GO						
2		ITEM-00002	SHIPMENT: REFUBRISHMENT OF DANFOSS 1.5 "DSVTHE SCOPE OF WORK FOR REFURBISHMENT OF EUROSAFE MAKE WATER MIST	1	EA				



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			SYSTEMMOTORIZED DRY SECTI						
			ONAL VALVES [SIZES 1INCH & 1.5 INCH] SHALL						
			INCLUDE,NOT LIMITED TO THE FOLLOWING,						
			INSPECTION, PREPARATIONS AND						
			REPLACEMENTOF PARTS AS						
			APPLICABLE AS FOLLOWS:-INSPECTION AND						
			PREPARATION##THE CONTRACTOR MUST HAVE						
			EXPERIENCE IN REPAIR AND RECTIFICATION						
			OFEUROSAFE MAKE						
			HP WATER MIST SYSTEM.##CLEAN INTERNAL						
			COMPONENTS USING SUITABLE						
			SOLVENTS.##REMOVE SCALE, RUST, OR DEBRIS						
			USING BRUSHES##DRY ALL PART						
			S THOROUGHLY WITH LINT-FREE CLOTHS OR						
			COMPRESSED AIR.##CHECK BALL SURFACE FOR						
			SCORING, PITTING, OR CORROSION.##EXAMINE						
			SEATS AND SEA						
			LS FOR WEAR, DEFORMATION, OR						
			CRACKS.##INSPECT STEM AND TEFLON PAD AND O						
			RINGS OF THE BALL VALVE.##CHECK ACTUATOR						
			FOR SMOOTH OPERATIO						
			N, AND SIGNAL RESPONSE.##THE REPLACEMENT						
			OF COMPONENTS IF INVOLVED SHALL BE OF SAME						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			MAKE &MODEL OF THAT OF OEM.##ALL THE						
			TESTING SHA						
			LL BE CARRIED OUT IN THE VENDOR TEST						
			FACILITY ORANY APPROVED TESTING						
			LABORATORY.##A PROPER INSPECTION REPORT						
			WITH PHOTOGRAPHS SHALL						
			BE SUBMITTED TODEWACASE: -1 ACTUATOR IS						
			WORKING PERFECTLY, AND VALVE NEED TO BE						
			RECTIFIEDRECTIFICATION OF DSV##REPLACE						
			DAMAGED TEFLO						
			N PAD ON THE BALL VALVE.##LAP THE BALL AND						
			SEATS IF MINOR DAMAGE EXISTS.##LUBRICATE						
			MOVING PARTS WITH APPROPRIATE VALVE						
			GREASE.##REA						
			SSEMBLE VALVE IN CORRECT ORIENTATION AND						
			TORQUE FASTENERS TOSPECIFICATION.##DO THE						
			HYDRAULIC STATIC PRESSURE TEST WITH						
			PRESSURE OF 2						
			10 BARS FOR15 MIN.##IF THE PRESSURE TEST IS						
			PASSED MOUNT ACTUATOR, ALIGN TO						
			PREVIOUSPOSITION, AND TIGHTEN						
			PROPERLY.##CONNECT ELECTRI						
			CAL LINES AS PER SPECIFICATIONS.##CALIBRATE						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ACTUATOR STROKE USING MANUAL						
			TUNING.##ENSURE SMOOTH OPERATION OF VALVE						
			AND ACTUATOR ASSE						
			MBLY.##IF THE PRESSURE TEST FAILS DISPOSE						
			THE VALVE##PROPOSE AND ASSEMBLE NEW						
			VALVE TO THE ACTUATOR AND TEST						
			AGAIN.##GENERATE VALVE						
			REFURBISHMENT/REPLACEMENT REPORT WITH						
			BEFORE AND AFTERPHOTOGRAPHS##WARRANTY						
			FOR THE NEW VALVE SUPPLIED: 1 YEAR CASE: -2						
			VALVE IS FUN						
			CTIONING PERFECTLY, AND ACTUATOR IS NOT						
			WORKING##CHECK ACTUATOR FOR SMOOTH						
			OPERATION, AND SIGNAL RESPONSE.##CLEAN THE						
			MOVING PARTS A						
			ND LUBRICATE##CONNECT ELECTRICAL LINES AS						
			PER SPECIFICATIONS AND TEST##IF THE VALVE IS						
			NOT WORKING, REPLACE THE ACTUATOR [ULLI 10						
			SE						
			RIESJAND ASSEMBLE TO THE VALVE AND DO THE						
			TESTING.##CONNECT ELECTRICAL LINES AS PER						
			SPECIFICATIONS.##CALIBRATE ACTUATOR						
			STROKE USING						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			MANUAL TUNING.##ENSURE SMOOTH OPERATION OF VALVE AND ACTUATOR ASSEMBLY.##DO THE HYDRAULIC STATIC PRESSURE TEST WITH PRESSURE OF 210 BARS FOR15 MIN.##GENERATE VALVE REFURBISHMENT/REPLACEMENT REPORT WITH BEFORE AND AFTERPHOTOGRAPHS##WARRANTY FOR THE NEW ACTUATOR SU PPLIED: 1 YEARTHE WORK SHALL BE COMPLETED WITHIN 4 WEEKS FROM DATE OF ISSUANCE OF PO.FOR ANY RELATED QUERIES AND FURTHER INFORMATION , CONTACT MR. VISHNUVIJAY [EMAIL: VISHNU.VIJAY@DEWA.GOV.AE, MOB: 0509463644] OR MR. ANEEZHUSSAIN [EMAIL: ANEEZ.ABDULRAZAK@DEWA.GO						
3		ITEM-00003	DXBCRSTL: REFUBRISHMENT OF DANFOSS 1"DSVTHE SCOPE OF WORK FOR REFURBISHMENT OF EUROSAFE MAKE WATER MIST SYSTEMMOTORIZED DRY SECTIONA L VALVES [SIZES 1INCH & 1.5 INCH] SHALL INCLUDE,NOT LIMITED TO THE FOLLOWING,	1	EA				



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			INSPECTION, PREPARATIONS AND						
			REPLACEMENTOF PARTS AS AP						
			PLICABLE AS FOLLOWS:-INSPECTION AND						
			PREPARATION##THE CONTRACTOR MUST HAVE						
			EXPERIENCE IN REPAIR AND RECTIFICATION						
			OFEUROSAFE MAKE HP						
			WATER MIST SYSTEM.##CLEAN INTERNAL						
			COMPONENTS USING SUITABLE						
			SOLVENTS.##REMOVE SCALE, RUST, OR DEBRIS						
			USING BRUSHES##DRY ALL PARTS T						
			HOROUGHLY WITH LINT-FREE CLOTHS OR						
			COMPRESSED AIR.##CHECK BALL SURFACE FOR						
			SCORING, PITTING, OR CORROSION.##EXAMINE						
			SEATS AND SEALS						
			FOR WEAR, DEFORMATION, OR						
			CRACKS.##INSPECT STEM AND TEFLON PAD AND O						
			RINGS OF THE BALL VALVE.##CHECK ACTUATOR						
			FOR SMOOTH OPERATION,						
			AND SIGNAL RESPONSE.##THE REPLACEMENT OF						
			COMPONENTS IF INVOLVED SHALL BE OF SAME						
			MAKE &MODEL OF THAT OF OEM.##ALL THE						
			TESTING SHALL						
			BE CARRIED OUT IN THE VENDOR TEST FACILITY		1				



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			ORANY APPROVED TESTING LABORATORY.##A						
			PROPER INSPECTION REPORT WITH						
			PHOTOGRAPHS SHALL BE						
			SUBMITTED TODEWACASE: -1 ACTUATOR IS						
			WORKING PERFECTLY, AND VALVE NEED TO BE						
			RECTIFIEDRECTIFICATION OF DSV##REPLACE						
			DAMAGED TEFLON P						
			AD ON THE BALL VALVE.##LAP THE BALL AND						
			SEATS IF MINOR DAMAGE EXISTS.##LUBRICATE						
			MOVING PARTS WITH APPROPRIATE VALVE						
			GREASE.##REASSE						
			MBLE VALVE IN CORRECT ORIENTATION AND						
			TORQUE FASTENERS TOSPECIFICATION.##DO THE						
			HYDRAULIC STATIC PRESSURE TEST WITH						
			PRESSURE OF 210						
			BARS FOR15 MIN.##IF THE PRESSURE TEST IS						
			PASSED MOUNT ACTUATOR, ALIGN TO						
			PREVIOUSPOSITION, AND TIGHTEN						
			PROPERLY.##CONNECT ELECTRICAL						
			LINES AS PER SPECIFICATIONS.##CALIBRATE						
			ACTUATOR STROKE USING MANUAL						
			TUNING.##ENSURE SMOOTH OPERATION OF VALVE						
			AND ACTUATOR ASSEMBL						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			Y.##IF THE PRESSURE TEST FAILS DISPOSE THE						
			VALVE##PROPOSE AND ASSEMBLE NEW VALVE TO						
			THE ACTUATOR AND TEST AGAIN.##GENERATE						
			VALVE REF						
			URBISHMENT/REPLACEMENT REPORT WITH						
			BEFORE AND AFTERPHOTOGRAPHS##WARRANTY						
			FOR THE NEW VALVE SUPPLIED: 1 YEAR CASE: -2						
			VALVE IS FUNCTI						
			ONING PERFECTLY, AND ACTUATOR IS NOT						
			WORKING##CHECK ACTUATOR FOR SMOOTH						
			OPERATION, AND SIGNAL RESPONSE.##CLEAN THE						
			MOVING PARTS AND						
			LUBRICATE##CONNECT ELECTRICAL LINES AS PER						
			SPECIFICATIONS AND TEST##IF THE VALVE IS NOT						
			WORKING, REPLACE THE ACTUATOR [ULLI 10						
			SERIE						
			SJAND ASSEMBLE TO THE VALVE AND DO THE						
			TESTING.##CONNECT ELECTRICAL LINES AS PER						
			SPECIFICATIONS.##CALIBRATE ACTUATOR						
			STROKE USING MA						
			NUAL TUNING.##ENSURE SMOOTH OPERATION OF						
			VALVE AND ACTUATOR ASSEMBLY.##DO THE						
			HYDRAULIC STATIC PRESSURE TEST WITH						



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

CLOSING DATE : 05.08.2025

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			PRESSURE OF 210 BA RS FOR15 MIN.##GENERATE VALVE REFURBISHMENT/REPLACEMENT REPORT WITH BEFORE AND AFTERPHOTOGRAPHS##WARRANTY FOR THE NEW ACTUATOR SUPPL IED: 1 YEARTHE WORK SHALL BE COMPLETED WITHIN 4 WEEKS FROM DATE OF ISSUANCE OF PO.FOR ANY RELATED QUERIES AND FURTHER INFORMATION, C ONTACT MR. VISHNUVIJAY [EMAIL: VISHNU.VIJAY@DEWA.GOV.AE, MOB: 0509463644] OR MR. ANEEZHUSSAIN [EMAIL: ANEEZ.ABDULRAZAK@DEWA.GOV.A E ,MOB: 0559660850]						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

DXBCRSTL:REFUB. of EUROSAFE WMS 1"DSV

Club PR 1032503604,1032503623 <(>&<)> 1032503624 into single RFx

STANDARD TERMS & CONDITIONS

1) Prices should be 'DDP' delivery duty paid at DEWA stores.



RFQ NUMBER : 2332501929

DATE : 30.07.2025

REQ No : 1032503604

REQ TITLE : TREATPLT

DELIVERY LOCATION

- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP